

General Environmental Incident Summary

Incident: 3670 **Date/Time Notice:** 2/28/2015 1845 **DEM Incident No:**
Responsible Party: Cal-Kern LLC
Date Incident: 2/28/2015 **Time Incident:** 1745 **Duration:** 3 hours
County: McKenzie **Twp:** 149 **Rng:** 98 **Sec:** 30 **Qtr:**
Lat: 47.69819 **Long:** -103.28310 **Method:** Interpolation from map
Location Description: Driver was traveling north on US 85. mm 131, north of Teddy Roosevelt Nat'l Park, North Unit
Submitted By: Beverly Hinesley **Affiliation:** Secretary
Address: 2000 North 16th Street # 4
City: Bismarck **State:** ND **Zip:** 58501

Received By:

Contact Person: Beverly Hinesley
702 4th Street East
Williston, ND 58801

Distance Nearest Occupied Building: 1 Miles **Release Contained:** Yes
Type of Incident: Vehicle Accident
Description of Released Contaminant: Diesel
Volume Spilled: 150.00 gallons **Ag Related:** No
EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

This is what the driver related to me. He was traveling north on US 85 on a two lane hwy. He saw something laying in the road he started to move onto the left lane but could not due to on coming traffic. He then moved to the right to straddle the object because there was no shoulder to drive on. The object was flat from what he could see at that time. Just before he got to it he realized there was a piece of it sticking up about 2 ft. at this time all he could do was continue. After he got over the object he looked in his mirror and could tell he was losing some sort of fluid. He pulled over at the safest spot and could see marker 131. He got out of the truck saw there was diesel and he had no way to stop it so he called 911.

Risk Evaluation:

Diesel is flammable

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 05 - air and soil

Potential Environmental Impacts:

Diesel fuel Impact to plant life

Action Taken or Planned:

Absorbent & Safety Solutions Was called for clean up.
Minot, ND 58701
1 701-838-4558

Wastes Disposal Location: Bakken Western Incinerator
Newalta for the solid material from the hydro vac

Agencies Involved: 911

Updates

Date: 2/28/2015 **Status:** Reviewed; Followup Required **Staff:** Roberts, Kris

Updated Volume:

Notes:

Vehicle/debris incident ruptured fuel line, causing loss of approximately 150 gallons of diesel to the road ditch. Culvert under highway in immediate vicinity. North of the park, outside park boundaries. Response crew was deployed. Report came in on NDDoH response phone on 2/28. Followup is necessary.

Date: 3/4/2015 **Status:** Inspected **Staff:** Crowdus, Kory

Updated Volume:

Notes:

On site 3/4/15 at 2:45 p.m. There is a noticeable trail of staining approximately 200 feet in the northbound lane and shoulder on Hwy 85. The culvert in the ditch has some absorbent material in it, but due to snowfall it is difficult to determine the extent of impact to the ditch. More followup is required.